

FAULT DETECTION - LEAKY BUILDINGS - MOISTURE TESTING - PROPERTY DAMAGE MECHANICAL - STRUCTURAL - THERMAL - COMMERCIAL - INDUSTRIAL - MARINE RESIDENTIAL - FREE QUOTES - FACTORIES - NEW HOUSES - INDUSTRIAL ELECTRICAL SWITCHBOARDS - ENERGY EFFICIENCY OF INSULATION IN COOL STORES WEATHER PROOF TESTING OF WINDOWS, WALLS & CEILINGS - BLOWER DOOR TESTING PROPERTY DRONE IMAGES & VIDEOS - VISIT US ONLINE

0800 183 490

021 183 4944

www.thermfit.nz





ในตลาดปัจจุบันการใช้พลังงานอย่างมีประสิทธิภาพเป็นข่าวดีสำหรับโครงการเกือบทุกโครงการ แม้ว่าคุณจะใส่หน้าต่างและประตูที่ดีที่สุดคุณก็ยังสามารถสูญเสียการต่อสู้ด้านพลังงานในพื้นที่อื่น ๆ ของบ้านได้ ผ่านบริการทดสอบของเราคุณสามารถดูว่ามีปัญหาอื่น ๆ ที่อาจเกิดขึ้นได้อย่างไร ฉนวนกันความร้อนที่ไม่ดีช่องว่างรอบ ๆ ท่อและช่องระบายความชุ่มชื้นและปัญหาอื่น ๆ

สามารถทำให้การติดตั้งหน้าต่างและหน้าต่างของคุณดูไม่เป็นไปตามที่คาดหวัง การถ่ายภาพด้วยความร้อนจะกระทำโดยใช้กล้องที่มีความไวต่อความร้อนสูงซึ่งแสดงให้เห็นถึงบริเวณที่ความร้อนล้น มีหลายพื้นที่ของบ้านที่หลวมจำนวนมหาศาลของพลังงานนอกเหนือจากหน้าต่างและประตู เรามีการจัดซื้อ "การตรวจสอบความร้อนและการสำรวจความชื้น" ที่เป็นความลับและตั้งอยู่ในเนลสัน แต่เดินทางไปในภูมิภาคนี้

In today's market place energy efficiency is a buzz word for almost any project. Even if you put in the best windows and doors, you can still be losing the energy battle in other areas of the home. Through our testing services you can see what other issues you may be having. Bad insulation, gaps around pipes and outlets, moisture penetration and other issues can make your door and window installation look like it is not performing to expectations. Thermal Imaging is performed with an infra-red heat sensitive camera that clearly shows areas where heat is escaping. There are many areas of a home that loose vast amounts of energy besides the windows and doors. We provide confidential prepurchase "Thermal Inspections & Moisture Surveys" and are based in Nelson but travel the region.